



Section 11



CON-STRUCT, INC.
1710 E. Main, P.O. Box 658
Marshalltown, Iowa 50158
Phone 515/752-1865



\$649⁴⁷

NAME WAKE FIELD


Section _____ Township _____ County _____

Contractor Ralph Wolff Date Installed MAY 1988

Amount of Tile Installed: 5" _____ 6" 108' 8" _____
10" 26' 12" _____ Larger _____

Regular inspection of the tile system is essential. Prompt repair of any failure will keep the system in working order and maintenance costs low.

CON-STRUCT, INC.
1710 E. Main, P.O. Box 658
Marshalltown, Iowa 50158
Phone 515/752-1865



Sec. 11

NAME WAKEFIELD # 975

Section _____ Township _____ County _____

Contractor Rich Smith Date Installed Nov. 1990

Amount of Tile Installed: 5" 1239' 6" _____ 8" _____
10" _____ 12" _____ Larger _____

Regular inspection of the tile system is essential. Prompt repair of any failure

B-200

WAKEFIELD FARMS
TILE MAP - HOME FARM

4
62.4


B-363
10.0

B-404

B-413

B-437

12



EXISTING TILE

2 2590 ft. 5" Plastic

TILE INSTALLED AUG, 1985


west side 2049'
NE corner 864'
east side 356'
SE corner 1036'

3
17.2

B-437

19.0

CON-STRUCT, INC.
1710 E. Main, P.O. Box 658
Marshalltown, Iowa 50158
Phone 515/752-1865



NAME IFM

Section _____ Township _____ County STORY

Contractor Bob Smith Date Installed Nov. 1986

Amount of Tile Installed: 5" 1723' 6" _____ 8" _____
10" _____ 12" _____ Larger _____

Regular inspection of the tile system is essential. Prompt repair of any failure will keep the system in working order and maintenance costs low.